Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: TYLER 1-19H

Field Name: UPLAND Well File #: 21451

Date Incident:2/15/2015Time Incident:11:28Facility ID Number:County:DIVIDETwp:161Rng:96Sec:19Qtr:

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 4 Barrels 4 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/14/2016 Clean Up Concluded: 2/16/2015

Risk Evaluation:

None

Areal Extent:

All fluid contained inside treater dike.

Potential Environmental Impacts:

Minimal after clean-up.

Action Taken or Planned:

Standing fluid was recovered by vac truck. Impacted material will be removed and taken to disposal.

Wastes Disposal Location: TBD

Agencies Involved: Notified Tom Delling NDIC by phone on 2/15/2015 at 5:38 PM CT

Updates

Date: 2/16/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.